SEAL AREA NO COPY PRINT MINIMUM 3.0" FROM END

KEEP TEXT/LOGOS & COPY WITHIN DOTTED LINE


0.50"




← 0.50"


72477


Composted Manure











Ready to use

Loosens soil

NET WT. 40 LBS. / 18 KG





CE Composted Manure

NET WT. 40 LBS./ 18 KG







84 Business Park Drive, Suite 309 TRINITY PACKAGING Armonk, NY 10504 **CORPORATION TECHNICAL INKS** Office: 914-273-4111 Fax: 914-239-4858 **DO NOT PRINT** DIE LINE **JOB INFORMATION PRINTING INKS** TP No.: CP4115 **INK NAME ANGLE INK COVERAGE % INK COVERAGE SQ INCH Description:** Markman Peat Ace 40lb Composted Manure 55 2.98% 15.85 sq in PANTONE 186 C 67.5 PANTONE 354 C 19.59 sq in 55 7.5 3.68% **Customer Part No.:** PANTONE 471 C 51.02 sq in 67.5 9.59% Die Size: 28.0000" x 19.0000" 28.78 sq in LINE BLACK C 37.5 5.41% Finish Bag Size: 19 x 28" UPC Code No.: 082901724773 UPC Type: UPC-A Barwidth Reduction: 0.005 inch **Print Direction:** 15-Sep-16

PACKAGING YOUR BRAND SINCE 1917

0.75"

SEAL AREA NO COPY PRINT MINIMUM 3.0" FROM END

KEEP TEXT/LOGOS & COPY WITHIN DOTTED LINE



ACE

Composted Manure

DIRECTIONS AND USES

FLOWER & VEGETABLE GARDENS

Broadcast 10 lbs. of Ace Composted Manure per 100 sq. ft. before planting. Mix well into soil.

For trenching use 3 lbs. of Ace Composted Manure per 100 linear feet and mix with soil in bottom of trench.

SHRUBS & TREES

Mix 1 part Ace Composted Manure with 3 parts soil and place in bottom

Guaranteed Analysis Total Nitrogen (N)	0.05-0.05-0.05 0.05%
Available Phosphate (P ₂ 0 ₅)	
Available Potash (K ₂ 0)	0.05%

ROSES

Place mixture of 1 part Ace Composted Manure and 3 parts soil in bottom of hole when planting. Cover mixture with layer of soil then set plants.

POTTING

Mix 1 part Ace Composted Manure with 4 parts soil.

HOUSE PLANTS

Use one level tablespoon of Ace Composted Manure for every inch of pot diameter. Mix and water.


Derived from Composted Manure and

Manufactured in USA for Ace Hardware Corp. Oak Brook, Illinois 60523, USA ©2016 www.acehardware.com

Packaged By: Markman Peat Corporation P.O. Box 777 Le Claire, IA 52753 WWW.MARKMANPEAT.COM







← 0.75"

of hole when planting or transplanting.

INGREDIENTS:

Peat.

ARTWORK RELEASE FORM



Please read the following instructions carefully. Your order is being held pending return of this form and the attached artwork proof.

We are pleased to submit the attached artwork for your approval.

PLEASE PROOFREAD AND CLEARLY INDICATE ANY CORRECTIONS.

By signing this form and approving the attached proof, you assume full responsibility for content accuracy. Trinity Packaging Corporation is not responsible for errors, omissions or changes if not noted below, and on the following proof. While Trinity Packaging Corporation adheres to strict procedures whenever a custom printed item is made, there are given variances that can not be avoided. Be sure to bring to our attention any print concerns you may have, so that we can pay special attention to or dialogue with you about that particular concern.

PLEASE BE SURE THE ATTACHED PROOF IS CORRECT



90 Industrial Ave. Rocky Mount, VA 24151 540-489-9915 FAX 540-489-6224

(Please intial to indicate your approval)

 Bag/Label Dimensions
 Art Dimension & Placement
 Ink Colors (Check PMS numbers closely)
 Film Color
 Copy and Spelling
 Phone Numbers, Website, ETC.
 Barcode Number (If Applicable)
 Over / Under Run Potential

Please return the signed Artwork Release Form and signed Artwork Proof to your sales agent or Joey Meador Email: jmeador@trinitypackaging.com

Your order will not be processed until the signed Artwork Release Form and Artwork Proof are returned

Artwork information	
CP:	
TP:.	
Descr.:	
Date:	

(Please check one of the boxes below sign and date)

Please proceed to production.
I have noted corrections on the artwork. I require an additional proof with corrections.

Authorized Signature and Date

CUSTOMER CORRECTIONS OR COMMENTS:

If submitting corrections via email, please indicate that here.